

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 19 7S92W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4021 Erosion & transport of sediment off location/insufficient BMP's (S/SW edge of location near Summit meter house)



Photo # 4022 Erosion & transport of sediment off location/insufficient BMP's (S/SW edge of location near Summit meter house)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4038 Rill erosion & transport of sediment (N/NE area of pad)



Photo # 4040 Rill erosion & transport of sediment (N/NE area of pad)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4041 Rill erosion & transport of sediment (N/NE area of pad)



Photo # 4042 Rill erosion & transport of sediment (N/NE area of pad)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



**Photo # 4010 Geotextile/liner & erosion observed
approximately 25-35 yards S/SW of location**



**Photo # 4011 Geotextile/liner & erosion observed
approximately 25-35 yards S/SW of location**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4012 Geotextile/liner & erosion observed approximately 25-35 yards S/SW of location



Photo # 4013 Geotextile/liner & erosion observed approximately 25-35 yards S/SW of location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



**Photo # 4014 Geotextile/liner & erosion observed
approximately 25-35 yards S/SW of location**