

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2023

Submitted Date:

07/28/2023

Document Number:

708901161

FIELD INSPECTION FORMLoc ID 335221 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210527	WELL	PR	03/12/1981	GW	045-06283	CLOUGH 112	PR
272673	WELL	PR	03/30/2005	GW	045-10127	CLOUGH RWF 512-21	PR
272675	WELL	PR	01/01/2023	GW	045-10126	CLOUGH RWF 412-21	PR
274171	WELL	PR	06/14/2005	GW	045-13341	CLOUGH RWF 612-21	PR

General Comment:**CECMC Inspection Report Summary**

On 07/28/2023 at approximately 09:16 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH 112 pad.

Location # 335221 in Garfield County Colorado.

Please refer to inspection 708900283 conducted on 04/12/2023, previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas.

Location is approximately 241 yards from a creek that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/Split pad - Wellheads only, production equipment for these 4 wells is located on the RMV 7-21 pad/production facility, location # 323900

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	CLOUGH 112 well is not on plunger lift The 3 other wells are on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210527 Type: WELL API Number: 045-06283 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well is not on plunger lift

Corrective Action:

Date:

Facility ID: 272673 Type: WELL API Number: 045-10127 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 272675 Type: WELL API Number: 045-10126 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 274171 Type: WELL API Number: 045-13341 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
Gravel						Sparse in some areas
		Ditches				
		Compaction				
		Culverts				
Compaction						Small areas of light compaction

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Remote location/Split pad - Wellheads only, production equipment for these 4 wells is located on the RMV 7-21 pad/production facility, location # 323900	smelserw	07/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901162	Inspection 708901161 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198991
708901163	Inspection 708901161 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198992