

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2023

Submitted Date:

07/29/2023

Document Number:

708901167

FIELD INSPECTION FORM

Loc ID 323886 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211096	WELL	PR	09/06/1994	GW	045-06855	CLOUGH RMV 3-20	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 07/28/2023 at approximately 09:00 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 3-20 pad. Location # 323886 in Garfield County Colorado.
Please refer to inspection 708900263 conducted on 04/11/2023 & inspection 708901081 conducted on 07/19/2023, previous corrective actions have been completed.
Location is within High Priority/Density Habitat areas & within close proximity to Bald Eagle Roost Site.
Location is within close proximity to multiple creeks/drainages that contribute to the Colorado River.
While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Remote location - Shared facilities with the CLOUGH RMV 213-20 pad, location # 335335

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible. Bradenhead line is conected to flow line.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	300 BBLs	HEATED STEEL AST		,
Comment:	Fresh water for fire suppression Separate containment				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)	Fresh water	
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Separate containment				
Corrective Action:			Date:		

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)	80 bbl			
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 211096 Type: WELL API Number: 045-06855 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
		Gravel				Sparse in sections
Compaction						Small areas of light compaction
Gravel						Sparse in some areas
		Ditches				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Split pad/Remote location - Shared facilities with the CLOUGH RMV 213-20 pad, location # 335335	smelserw	07/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901168	Inspection 708901167 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199017
708901169	Inspection 708901167 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199018