

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3920 From entrance to location



Photo # 3921 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050

Jul 27, 2023 at 10:24:55 AM



Photo # 3922 Location

Jul 27, 2023 at 10:25:23 AM



Photo # 3923 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3924 Location



Photo # 3925 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3926 Location



Photo # 3927 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3928 Location



Photo # 3930 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3933 Unused supplies



Photo # 3934 Unused supplies

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3935 Trash



Photo # 3937 Stained soils & gravel near FED 19-13D wellhead

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19EB Pad
Location #: 431050



Photo # 3940 Stained soils & gravel near 30-4A wellhead



Photo # 3942 Stained soils & gravel near wellheads

Inspection Photos

Location Name: CAERUS PICEANCE LLC O19EB Pad

Location #: 431050



Photo # 3946 Stained soils & gravel



Photo # 3947 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC O19EB Pad

Location #: 431050



Photo # 3949 Stained soils & gravel



Photo # 3950 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC O19EB Pad

Location #: 431050



Photo # 3952 Stained soils & gravel



Photo # 3944 Unused equipment & stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC O19EB Pad

Location #: 431050



Photo # 3971 Unused equipment & stained soils & gravel



Photo # 3963 Debris