

TEP
PA 13-34
Location ID:
335436



Well heads



Tank battery



TEP
PA 13-34
Location ID:
335436



Separators and lack of access to calibration cards



Cut slope lacks stabilization and Weeds have turned in to debris

TEP
PA 13-34
Location ID:
335436



Weeds have turned in to debris



Lack of stabilization, erosion and sediment migration encroaching on production equipment

TEP
PA 13-34
Location ID:
335436



Lack of stabilization, erosion and sediment migration encroaching on production equipment



Lack of stabilization, erosion and sediment migration encroaching on production equipment

TEP
PA 13-34
Location ID:
335436



Lack of stabilization and erosion



Lack of stabilization and erosion