

Construction & Stormwater Inspection

July 20, 2023

Operator: GMT Exploration Co, #10243

Location ID: 478822

Inspection Document # 709400373

Elbert, CO

SENW, 10 6S64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Vulcan 6-64 10-8

Location ID:478811



Photo 1. Photo of location sign.



Photo 2. Photo of site entrance. .

Inspection Photos

Location Name: Vulcan 6-64 10-8

Location ID:478811



Photo 3. Photo of Trash at entrance of pad.



Photo 4. Trash on site.

Inspection Photos
Location Name: Vulcan 6-64 10-8
Location ID:478811



Photo 5. Photo of trash spilling out of bag onsite.



Photo 6. Photo of Northeast corner slough off.

Inspection Photos

Location Name: Vulcan 6-64 10-8

Location ID:478811



Photo 7. Photo of erosion from stormwater



Photo 8. Photo of wattle undermined by stormwater.

Inspection Photos

Location Name: Vulcan 6-64 10-8

Location ID:478811



Photo 9. Photo of stormwater by passing rock check dam in access road.



Photo 10. Photo of pipe parallel to access road capturing sediment carried off site by stormwater.

Inspection Photos

Location Name: Vulcan 6-64 10-8

Location ID:478811



Photo 11. Photo of rock check dam in access road that has been tunnelled under by stormwater.



Photo 12. Rock check dam in access road filled with sediment, stormwater has bypassed the BMP.