

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/20/2023

Submitted Date:

07/31/2023

Document Number:

709400373

**FIELD INSPECTION FORM**
 Loc ID 478811 Inspector Name: WOLD, REED On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
		w.eberhardt@gmtexploration.com	
		mblair@gmtexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478811	LOCATION	AC			-	Vulcan 6-64 10-8 Pad	RI

**General Comment:**

This is a follow up stormwater and interim inspection, from previous inspection conducted on 6/7/2023 Document Number: 709400227.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash observed onsite.		
Corrective Action:	Comply with Rule 606.d.	Date:	08/04/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [North east corner of location has sloughed off due to heavy rains. Access road rock check dams have been bypassed or tunneled under by stormwater, erosion around culvers inlets and outlets. A large amount of sediment was captured by piping running parallel to the access road from erosion to access road. These were documented on the last inspection on 6/7/2023.](#)

Corrective Action: [Comply with rule 1002.f. Stormwater Management](#)

Date: 08/04/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400374	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6200434">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6200434</a>