

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 4212 From entrance to location



Photo # 4213 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 4214 Location



Photo # 4215 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 4216 Location



Photo # 4217 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 594 From inspection 708900778 conducted on 06/15/2023 Unused equipment/ECD is disconnected



Photo # 4223 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 595 From inspection 708900778 conducted on 06/15/2023 Unused equipment/ECD is disconnected



Photo # 4228 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 4235 Unused equipment/ECD is disconnected




Photo # 4245 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 4246 ECD line disconnected at tank battery



Photo # 4248 ECD line disconnected at tank battery

