

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2023

Submitted Date:

08/01/2023

Document Number:

698600855**FIELD INSPECTION FORM**Loc ID 302991 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.co m	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252228	WELL	PR	04/01/1977	GW	125-06097	STONE 1-26	PR

**General Comment:**[Routine Inspection.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Well sign on meter shed door.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	contents/quanity/Hazard			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Well sign			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Well sign at wellhead is unreadable.			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 09/01/2023
Emergency Contact Number:				
Comment:	No emergency contact information posted at well site.			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 09/01/2023
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Pump Jack belt drive guard noted on ground inside fencing.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Stock Panel Fencing around surface equipment at well location.			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Gas Meter Run	# 1			
Comment:	Digital Gas Meter Run. Meter Calibration/Test Log dated 10-21-22. Valves open.			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Supply Gas Liquids Knock Out Vessel.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter Run Liquids Knock Out Vessel.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Meter Shed		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.027850,-102.364190
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	210 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:



Inspected Facilities									
Facility ID:	252228	Type:	WELL	API Number:	125-06097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Valves at Meter Run are open. Electronic Well File reflects last Production/Status reported 5/1/2023 and Well Status as PR.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600862	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6202256">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6202256</a>