

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/02/2023

Submitted Date:

08/02/2023

Document Number:

708901219

**FIELD INSPECTION FORM**

Loc ID 324045 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211567	WELL	PR	08/02/2001	GW	045-07327	CLOUGH RMV #112-27	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 08/02/2023 at approximately 11:35 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 112-27 pad. Location # 324045 in Garfield County Colorado.  
Please refer to inspection 708900318 conducted on 04/20/2023, previous corrective action has been completed.  
Location is within High Priority/Density/NSO Habitat areas & Bald Eagle Nest & Roost Sites & in close proximity to Black Bear habitat area.  
Location is approximately 140 yards from the Colorado River  
While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Remote location - Shared facilities with the RMV 154-27 pad, location # 324162

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign weathered & cracking but still legible		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 211567 Type: WELL API Number: 045-07327 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in some areas
		Culverts				
		Compaction				
		Rip Rap				
		Gravel				Sparse in some sections
		Ditches				
Gravel						Sparse

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Split pad/Remote location - Shared facilities with the RMV 154-27 pad, location # 324162</span>	smelserw	08/02/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901220	Inspection 708901219 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204919">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204919</a>
708901221	Inspection 708901219 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204920">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204920</a>