

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2023

Submitted Date:

07/27/2023

Document Number:

697007772**FIELD INSPECTION FORM**Loc ID 449441 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449437	WELL	PR	03/01/2019	OW	123-44307	Windsor LV2 2	PR
449438	WELL	PR	01/01/2019	OW	123-44308	Windsor LV2 4	PR
449439	WELL	PR	11/01/2017	OW	123-44309	Windsor LV2 5	PR
449440	WELL	PR	11/01/2017	OW	123-44310	Windsor LV2 7	PR
449442	WELL	PR	03/01/2019	OW	123-44311	Windsor LV2 1	PR
449443	WELL	PR	11/01/2017	OW	123-44312	Windsor LV2 3	PR
449444	WELL	PR	01/01/2019	OW	123-44313	Windsor LV2 6	PR
449445	WELL	PR	07/01/2021	OW	123-44314	Windsor LV2 8	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 8		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol and chemical systems		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused methanol rack and secondary containment, see attached photo.		
Corrective Action:	Comply with Rule 606	Date:	08/18/2023
Type	DEBRIS		
Comment:	Dead vegetaion behind separators, around various locations in berms and underneath gas lines on the south side of the separators, see attached photos.		
Corrective Action:	Comply with Rule 606	Date:	08/18/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Calibration cards are current.		
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 4		
Comment:	Electric motors on LACT and VRU		
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Natural gas engines on compressors		
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automtaion array, solar array, methanol and chemical systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protections, ECD scrubbers, electrical systems, fire extinguishers with current inspection tags		
Corrective Action:			Date:
Type: Vertical Separator	# 5		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:	Pilots are on		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLs	STEEL AST		,	
Comment:	Maintenance tank					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	<100 BBLs	BV CONCRETE		,		
Comment:		60 bbls					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	<50 BBLs	BV CONCRETE		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	8	400 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							

Inspector Name: Peterson, Tom

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 449437 Type: WELL API Number: 123-44307 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449438 Type: WELL API Number: 123-44308 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449439 Type: WELL API Number: 123-44309 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449440 Type: WELL API Number: 123-44310 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449442 Type: WELL API Number: 123-44311 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 36 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449443 Type: WELL API Number: 123-44312 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 449444 Type: WELL API Number: 123-44313 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Inspector Name: Peterson, Tom

Facility ID: 449445 Type: WELL API Number: 123-44314 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/27/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 7/27/2023 at approximately 11:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Extraction Windsor LV2 14-M Pad location #449441 in Weld County, Colorado.</p> <p>While there, I observed debris and unused equipment on location. The following possible compliance issues were observed: Rule 606. a corrective action date of 8/18/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	07/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403479538	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197818
697007773	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197814