

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/27/2023

Document Number:

697602147

FIELD INSPECTION FORMLoc ID 311331 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242086	WELL	SI	11/01/2021	GW	123-09877	HLADKY-O'GORMAN 4	SI

General Comment:

This is an environmental inspection for Facility ID 242086. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Signage is adequate.

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds are overgrown at the wellhead.		
Corrective Action:	Comply with Rule 606.		Date: 08/03/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing around the excavation does not fully go around the excavation, leaving space for entry.		
Corrective Action:	Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.		Date: 08/03/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	242086	Type:	WELL	API Number:	123-09877	Status:	SI	Insp. Status:	SI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil		Inadequate		
Comment:	Unmarked stockpile was left on location with no liner. No indication if the stockpile is contaminated.			
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			Date: 07/31/2023

Spill/Remediation:

Comment:	Remediation excavation is open. Water was observed within the excavation. No sheen was observed on the water.			
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.			Date: 07/31/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403479345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197569
697602148	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197541