



Work Completion Report

Completion Header

Location Completed	SAKATA_RED_W-62N66W_6SENE
Alt Loc Name	SAKATA_RED_W-62N66W_6SENE
Visited On	07/28/2023
Performed By	Peerless
One-Call Number	
Red Zone Date	
Red Zone APC Rep	

Location Details

Location	SAKATA_RED_W-62N66W_6SENE
Location Type	Regulatory
Land Use - Insp	Crop
Crop Type	Corn
Latitude/Longitude	40.168447/-104.812858
Legal Address	(WELD) SENE 6 2N66W
COGCC Loc ID	336414
Land Rep	
Road Directions	None established
Land Use - Loc	Crop
Rec Contractor PO(s)	
Vendor PO(s)	



Work Completion Report



Work Completion Report

Work Completion Details

Assoc Work Task	Facility Weed Control
Assoc Job	SAKATA FEDERAL 8-6A
Work Summary	Mowed weeds surrounding battery and addressed pot holes on the pad.
SqFtAffected	
AcresAffected	0.20000
Seed Mix	None used
LandUse	Crop
CropType	Corn
SoilType	Clay Loam
CompletionDate	7/28/2023 12:00:00 AM
StabilizationDate	7/28/2023 12:00:00 AM
SeedingDate	
Mulch	None
Straw Bales	
SoilAmendType	None
SoilAmendUnits	
SoilAmendAmount	
SoilAmendRate	NA
Top Soil	NA
Topsoil Source	
General Notes	



Work Completion Report

Work Task Details

Work Task	Facility Weed Control
Job	SAKATA FEDERAL 8-6A
Requested On	7/12/2023 12:00:00 AM
Requested By	Tyler Scherden
Did COGCC issue a CA for Work?	No
Start By Date	
Due By Date	
Recur Frequency	
Status	Completed
Notes	Mow weeds surrounding battery, address pothole on pad if present.



Work Completion Report

Photos

Photo Type	General
Photo Name	Sakata 2
Photo Notes	
PhotoBlobID	



Photo Type	General
Photo Name	Sakata 3



Work Completion Report

Photo Notes

PhotoBlobID



Photo Type	Post-Completion
Photo Name	Post-Completion
Photo Notes	
PhotoBlobID	



Work Completion Report



Photo Type	Pre-Completion
Photo Name	Pre-Completion
Photo Notes	
PhotoBlobID	



Work Completion Report





Work Completion Report

Photo Type

Site Map

Photo Name


Site Map

Photo Notes

PhotoBlobID



Work Completion Report





Work Completion Report
