

Inspection Photos

API: 071-09018

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/24/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 1. Facing north at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 2. Facing southwest along the roadside. The rock check dams are not functioning or maintained and the roadside is not stabilized. Bare soil and rill erosion evident.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 3. Facing northwest near the location. A diversion berm was placed to divert stormwater off the road. This area was reseeded but has not yet established sufficient vegetation cover for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 4. Facing west toward the location. There is sediment deposition shown at red arrow. BMP's will need to be installed to prevent sediment migration offsite. The landowner has placed a shed on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 5. Facing northwest at the location. The well has been cut and capped below grade and there is no above ground well marker. All oil and gas equipment has been removed. The landowner has placed a shed on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 6. Facing toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 7. Facing northeast at the bottom of the fill slope. There are areas at the base of the fill slope that are not stabilized and have rill erosion occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 8. Facing northwest at the bottom of the fill slope. There are areas at the base of the fill slope that are not stabilized and have rill erosion occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 9. Facing northeast at the location. The well has been cut and capped below grade. All oil and gas equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 10. Facing northeast toward the cut slope. There are areas of bare soil and rill erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023

Inspection Photos



Photo 11. Facing northwest toward the cut slope. There appears to be some unstable rock along the cutslope which may fall onto the wellpad. BMP's will need to be installed for stabilization of the cut slope and rock/sediment movement.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09018 | Date: 7/24/2023