

TEP
MV 43-31
Location ID:
334912



Well heads



Well heads

TEP
MV 43-31
Location ID:
334912



Separators



Tank battery and signage is fading

TEP
MV 43-31
Location ID:
334912



BMP's on location



Cut slope lacks stabilization

TEP
MV 43-31
Location ID:
334912



Cut slope lacks stabilization



Cut slope lacks stabilization

TEP
MV 43-31
Location ID:
334912



Erosion on cut slope causing run on



Erosion on cut slope causing run on

TEP
MV 43-31
Location ID:
334912



Weeds turned into debris



Weeds turned into debris

TEP
MV 43-31
Location ID:
334912



Weeds turned into debris



Cut slope lacks stabilization