

TEP
PA 31-6
Location ID:
334920



Tank battery



Battery signage is becoming weathered

TEP
PA 31-6
Location ID:
334920



Separators



Well heads

TEP
PA 31-6
Location ID:
334920



Lack of stabilization and erosion



Lack of stabilization and erosion

TEP
PA 31-6
Location ID:
334920



Erosion



Sediment on access road

TEP
PA 31-6
Location ID:
334920



Culvert needs maintained



Sediment migrating from location

TEP
PA 31-6
Location ID:
334920



Sediment migrating from location