

Inspection Photos

API: 071-06101

Operator: MANZANO LLC

Inspection Date: 8/2/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 1. Drone aerial photo facing southwest toward the access road which is not reclaimed. There is a pipeline riser that has not been removed shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 2. Facing southwest along the access road. There is signs or erosion along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 3. Facing northwest toward the location which has not been recontoured or reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 4. There are 3 pipeline risers and a cement block that have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 5. Facing south at the location. There is a large erosion gully along the fill slope shown at red arrow..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 6. Facing southeast toward the location. A shallow pit remains shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 7. Facing southeast toward the cut slope which has signs of erosion gully's and rills.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06101 | Date: 8/2/2023

Inspection Photos



Photo 8. Facing west toward the location.

