

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



Location sign missing required information.



Access road to location

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



Wellhead sign lacking required information.



Debris

**GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283**



**Engine leakage. Stained soil.**



**Tank battery sign missing required information**

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



**Debris. Stained soil and gravel.**



**Stained soil. Gravel cover-up.**

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



Debris



Weed growth

**GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283**



**Debris. Open to wildlife.**



**Labels missing and illegible**

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



Debris



Debris

**GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283**



**No visible display of gas calibration**

**Weed growth**

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



**Thistle**



**Thistle**

GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283



Debris. Unidentified spill materials?



Location from Southwest corner

**GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283**



**Location from Southeast corner**

**Location from Northeast corner**

**GRMR Oil & Gas LLC  
Myers 19-11HA  
Loc ID: 441283**

**Description**

**Description**