

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2023

Submitted Date:

08/04/2023

Document Number:

708901240

FIELD INSPECTION FORM

Loc ID: 324124 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Findings:
 16 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258016	WELL	PR	06/01/2020	GW	045-07610	VASSAR/HEATH RMV 229-27	PR

General Comment:
 CECMC Inspection Report Summary
 On 08/04/2023 at approximately 10:47 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 229-27 pad. Location # 324124 in Garfield County Colorado.
 Please refer to inspection 708900534 conducted on 05/19/2023, previous corrective actions have been completed.
 Location is within High Priority/Density Habitat areas & Bald Eagle Nest & Roost Sites & in close proximity to NSO Habitat.
 Location is approximately 366 yards from the Colorado River.
 While there, I observed normal production operations.

 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug on bradenhead, bradenhead valve accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 258016 Type: WELL API Number: 045-07610 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Areas with light compaction
		Gravel				Sparse in some sections
		Culverts				
		Ditches				
Ditches						
		Rip Rap				
Gravel						Sparse in some areas
Check Dams						
Berms						
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901241	Inspection 708901240 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209091
708901242	Inspection 708901240 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209092