

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 06/14/2023 Document Number: 403379363

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10633 Contact Person: James Miller Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460 Address: 1801 CALIFORNIA STREET #2500 Email: jmiller@civiresources.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 473525 Location Type: Production Facilities Name: EDITH ANN-62N68W Number: 21NESE County: WELD Qtr Qtr: NESE Section: 21 Township: 2N Range: 68W Meridian: 6 Latitude: 40.123111 Longitude: -105.001647

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473542 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336416 Location Type: Well Site   
Name: JILLSON 'A'-62N68W Number: 21NWSE  
County: WELD No Location ID  
Qtr Qtr: NWSE Section: 21 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.122330 Longitude: -105.005940

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 04/25/2002  
Maximum Anticipated Operating Pressure (PSI): 175 Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Out of Service**

Date: 10/13/2022  Entire Line Removal  Partial Line Removal

**Description of Out of Service:**

The flowline servicing the Edith Ann 33-21 (05-123-20624) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 12/26/2019.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473541 Flowline Type: Wellhead Line Action Type: Out of Service

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 323300 Location Type: Well Site   
Name: EDITH ANN-62N68W Number: 21NESE  
County: WELD No Location ID  
Qtr Qtr: NESE Section: 21 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.121457 Longitude: -105.002196

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 05/04/1996  
Maximum Anticipated Operating Pressure (PSI): 185 Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Out of Service**

Date: 10/13/2022

Entire Line Removal

Partial Line Removal

**Description of Out of Service:**

The flowline servicing the Edith Ann 1-2 (05-123-12833) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 4/12/2018.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now out of service:  
12312833\_FL: services the Edith Ann 1-2 (05-123-12833)  
12320624\_FL: services the Edith Ann 33-21 (05-123-20624)  
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 06/14/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ **Director of COGCC** Date: \_\_\_\_\_

## Conditions of Approval

**COA Type**

**Description**

--	--

## Attachment Check List

**Att Doc Num**

**Name**

403433065	OFF-LOCATION FLOWLINE GIS SHP
-----------	-------------------------------

Total Attach: 1 Files

## General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval

Total: 0 comment(s)