

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

06/09/2023

Document Number:

403169208

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10575 Contact Person: James Miller
Company Name: 8 NORTH LLC Phone: (720) 984-7460
Address: 370 17TH STREET SUITE 5200 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 468102 Location Type: Production Facilities
Name: Marick 1, 7, 10-29 Tank Battery Number:
County: WELD
Qtr Qtr: NWSE Section: 29 Township: 11N Range: 61W Meridian: 6
Latitude: 40.895610 Longitude: -104.226813

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8N will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8N retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8N ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

NA

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 470789 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 306280 Location Type: Well Site

Name: MARICK-611N61W Number: 29NWSE

County: WELD No Location ID

Qtr Qtr: NWSE Section: 29 Township: 11N Range: 61W Meridian: 6

Latitude: 40.891030 Longitude: -104.227670

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375

Bedding Material: Native Materials Date Construction Completed: 05/28/2007

Maximum Anticipated Operating Pressure (PSI): 23 Testing PSI: 23

Test Date: 06/10/2017

OFF LOCATION FLOWLINE Abandonment Verification

Date: 06/21/2018

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

Flowline previously reported as abandoned on doc# 401671460.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 470790 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 305689 Location Type: Well Site

Name: MARICK-611N61W Number: 29SWNE

County: WELD No Location ID

Qtr Qtr: SWNE Section: 29 Township: 11N Range: 61W Meridian: 6

Latitude: 40.894810 Longitude: -104.226980

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375

Bedding Material: Native Materials Date Construction Completed: 11/29/2005

Maximum Anticipated Operating Pressure (PSI): 150 Testing PSI:

Test Date:

OFF LOCATION FLOWLINE Abandonment VerificationDate: 08/19/2022**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the Marick 7-29 (05-123-23360) was removed in its entirety via the open trench method. The trench was backfilled and the land surface was graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 470791 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATIONEquipment at End Point Riser: Separator**Flowline Start Point Location Identification**

Location ID: 306276 Location Type: Well Site
 Name: MARICK-611N61W Number: 29NENE
 County: WELD No Location ID
 Qtr Qtr: NENE Section: 29 Township: 11N Range: 61W Meridian: 6
 Latitude: 40.897710 Longitude: -104.222690

Equipment at Start Point Riser: Well**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
 Bedding Material: Native Materials Date Construction Completed: 05/22/2007
 Maximum Anticipated Operating Pressure (PSI): 130 Testing PSI: _____
 Test Date: _____

OFF LOCATION FLOWLINE Abandonment VerificationDate: 08/19/2022**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the Marick 1-29 (05-123-24342) was removed in its entirety via the open trench method. The trench was backfilled and the land surface was graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were removed:
 12319342FL: serviced the Marick 1-29 (05-123-24342)
 12323360FL: serviced the Marick 7-29 (05-123-23360)
 Updated GIS data attached.


I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 06/09/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____



Director of COGCC

Date: 8/7/2023

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403169208	Form44 Submitted
403399658	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

GIS	The GIS data associated with the 12324346FL flowline is not attached.	03/01/2023
-----	---	------------

Total: 1 comment(s)