

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



North Entrance to Location – Photo #05526



SE Corner of Location – Photo #05527

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



SE Corner of Location – Photo #05528



Wellheads – Photo #05539

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



Separators – Photo #05529



Tank Battery – Photo #05530

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



Open-Ended Load Line – Photo #05534



Open-Ended Load Line – Photo #05535

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



Location Lacks Stabilization – Photo #05537



Location Lacks Stabilization – Photo #05538

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05540**



Rill Erosion Cutting Through Lease Road – Photo #05610

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 8/7/2023



Rill Erosion Cutting Through Lease Road – Photo #05613



Check Dam Needs Maintenance – Photo #05611