

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



SE Corner of Location – Photo #05542



SW Corner of Location – Photo #05543

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



NE Corner of Location – Photo #05546



NW Corner of Location – Photo #05547

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



Wellheads – Photo #05545



Separators – Photo #05552

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



Tank Battery – Photo #05549



Tank Label Missing Tank Capacity – Photo #05550

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



**Separator Hatch Unsecured – Photo #05551**



**Rill Erosion Transporting Sediment to Nearby Watershed – Photo #05555**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



**Rill Erosion Transporting Sediment to Nearby Watershed –  
Photo #05556**



**Rill Erosion Cutting Through Lease Road – Photo #05610**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 8/7/2023



**Rill Erosion Cutting Through Lease Road – Photo #05613**

**Check Dam Needs Maintenance – Photo #05611**