

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2023

Submitted Date:

08/02/2023

Document Number:

702402161

**FIELD INSPECTION FORM**Loc ID 318288 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241041	WELL	PR	09/01/2022	OW	123-08829	MARTIN T. HART H 1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type			
Comment:	See Inspection Doc # 702401137 for related shared facilities and equipment.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	#		
Comment:	no indication of calibration		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1)	Date:	02/23/2023
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation, electric panel, meter box and transformers		
Corrective Action:		Date:	
Type:	#		
Comment:	See Inspection Doc # 702401137 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	electric motor		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	appears plumbed to surface		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 702401137 for related shared facilities and equipment.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 241041 Type: WELL API Number: 123-08829 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 8-2-2023 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 702401869 &amp; 702401437.</p> <p>Operator: KP Kauffman</p> <p>Location name: Martin T Hart H unit 1</p> <p>API #05-123-08829</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite and tank battery, SI at the time of inspection.</p> <p>During this inspection, I observed the following possible compliance issue has not been addressed and is now delinquent:</p> <p>430 gas measurment: no indication of meter calibration, CA date 2-23-2023.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/02/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403484917	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204249</a>
702402162	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204187">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6204187</a>