

## Van Buren Federal A2

COGCC Inspection # 712700438

Date completed 8/8/2023

Removed stained soil from around the wellhead

Removed stained soil from inside pump jack cage



Removed stained soil from around oil lift

