

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2023

Submitted Date:

08/09/2023

Document Number:

698600897

FIELD INSPECTION FORMLoc ID 337909 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

27 Number of Comments

11 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
, Engineering		dnr_cogccengineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Hickey, Mike		michael.hickey@state.co.us	
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289559	WELL	PR	04/01/2022	GW	125-10744	KILLIN 15-22-5-45	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action	L Repair and maintain lease road to comply with rule 603.I.	Date:	09/09/2023
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign at well location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents/Quanity/Hazard.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign at the remote Meter Shed.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/09/2023
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Production related equipment and debris left at remote Gas Meter Run location.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2023
Type	DEBRIS		
Comment:	Production related debris left inside fencing at well location.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2023
Type	WEEDS		
Comment:	Well location has vegetation growing inside fencing. Remote Gas Meter Run site is over grown with vegetation.		
Corrective Action:	Comply with Rule 606.	Date:	08/17/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock Panel Fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Inlet valve at Gas Meter Run is broken and will not go to fully closed position.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 08/25/2023
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed, not connected. Wellhead is leaking at the cap between the tubing and packing.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 08/08/2023
Type: Vertical Separator	# 1		
Comment:	Inside Meter Shed.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR BB. Gas Meter Run. Chart in Meter Box was found twisted inside Meter Box and undated. Meter Calibration/Test Log dated 7-16-20. Well Inlet Valve appears to be closed bad valve. Gas Outlet Valve closed. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 09/09/2023
Type: Other	# 1		
Comment:	Liquids Knock Out Vessel inside Meter Shed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Metal Meter Shed at remote Gas Meter Run.		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 08/20/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:	Located at remote Gas Meter Run off CR BB.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

Wells Served By Facilities Above**AirsID**

API Number

API Number

AirsID

125-10745

Venting:

Yes/No	YES		
Comment:	Wellhead is leaking gas from the Wellhead Cap between the tubing and packing.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	08/08/2023

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 289559 Type: WELL API Number: 125-10744 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed, not connected. Gas Meter Run Valves: Well inlet valve maybe closed, bad valve, Gas outlet valve closed, Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/09/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600910	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213157
698600911	Wellhead Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213158