

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 5526 From entrance to location



Photo # 5527 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 5528 From entrance to location



Photo # 5529 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 5530 Location



Photo # 5531 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 5532 Location



Photo # 5537 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC D13W Pad

Location ID: 334676



Photo # 5607 Open ended load line & tank valve leaking fluid



Photo # 5552 Tank valve leaking fluid

Inspection Photos

Location Name: CAERUS PICEANCE LLC D13W Pad

Location ID: 334676



Photo # 5571 Tank valve leaking fluid



Photo # 5590 Tank valve leaking fluid