

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2023

Submitted Date:

08/09/2023

Document Number:

698600900

FIELD INSPECTION FORMLoc ID 337967 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

25 Number of Comments

10 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Pesicka, Conor		conor.pesicka@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
, Engineering		dnr_cogccengineering@state.co.us	
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290424	WELL	PR	05/01/2022	GW	125-10815	STRUCKMEYER 6-22-5-45	PR

General Comment:

Routine Inspection.

Location				
Lease Road:				
Type	Access			
comment:	Two track off maintained county road. Two track has not been maintained			
Corrective Action:	Repair and maintain lease road to comply with rule 603.l.			Date: 09/09/2023
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Well sign posted on Meter Shed.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.			
Corrective Action:	Install sign to comply with Rule 605.a.			Date: 09/09/2023
Good Housekeeping:				
Type	WEEDS			
Comment:	Well location has vegetation growing inside fencing.			
Corrective Action:	Comply with Rule 606.			Date: 08/17/2023
Type	DEBRIS			
Comment:	Production related debris left inside wellhead fencing.			
Corrective Action:	Comply with Rule 606.			Date: 09/09/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Post and wire fencing.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Stock Panel Fencing is at well site but not assembled.			
Corrective Action:	Repair and maintain fencing to comply with rule 603.h			Date: 08/14/2023
Equipment:				
Type: Vertical Separator	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Located 4 deadmen. All markers are down.			

Corrective Action:	Install proper guy line markers per Rule 603.j		Date:	08/24/2023
Type: Pump Jack	# 0			
Comment:	Removed.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Metal Meter Shed.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve maybe closed, bad valve.			
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date:	08/25/2023
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Cement Pad. Pump Jack has been removed but cement pad is still on site.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Gas Meter Run. Chart in Meter Box dated 9-1-22. Meter Calibration/Test Log dated 7-16-20. Well Inlet Valve maybe closed. Gas Outlet Valve maybe closed. Water Outlet valve closed. Bad valves on flowlines.			
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date:	08/25/2023
Type: Bradenhead	# 0			
Comment:	Bradenhead inaccessible or not visible.			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date:	08/20/2023
Type: Prime Mover	# 0			
Comment:	Removed.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 290424 Type: WELL API Number: 125-10815 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve maybe closed, bad valve. Gas Meter Run Valves: Well inlet valve maybe closed, bad valve. Gas outlet valve maybe closed, bad valve. Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/09/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600914	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213661