

Inspection Photos

Location Name: Bowman 13-22-5-44

API Number: 125-09496



1. Well sign at well location.



2. View of Wellhead. Note Pump Jack barrier rails on Wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bowman 13-22-5-44
API Number: 125-09496



3. Concrete pad and production related debris left at location. Note vegetation.



4. View of Chart in Meter Box at time of inspection.

Inspection Photos
Location Name: Bowman 13-22-5-44
API Number: 125-09496

Omnimex Meter Test Report

Well Name Bowman 13-22-5-44 Date 8-25-20

Diff. Range 0 to 100 Static Range 0 to 150 Plate 250

Temp Average 60

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150)	75	75 (150)
0	0	0

Inspector Loy Kott

2023.08.08 15:20

5. View of Meter Calibration/Test Log inside of Meter House.



6. Location overview and unmarked marker.

Inspection Photos
Location Name: Bowman 13-22-5-44
API Number: 125-09496



7. Tank Battery sign out of bracket and face down on ground.



8. View of Steel Tank and Concrete Vault. Note Vegetation.

Inspection Photos
Location Name: Bowman 13-22-5-44
API Number: 125-09496



9. View of Fiberglass Tank. No Placards or Signage. Note vegetation.



10. Washed out containment berm in SW corner.

Inspection Photos
Location Name: Bowman 13-22-5-44
API Number: 125-09496



11. Electric pump in bottom of vault.



12. Tank Battery overview.