

NAME: BOMBARDIER 31-36, API #: 071-07081, INSP. # 695108545



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: AREA OF IMPACTED SOIL BETWEEN WELLHEAD AND PIT. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 9-9-2023.





PHOTO 5: ANTIFREEZE AND OILY WASTE IN PRIME MOVER SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 8-10-2023.





PHOTO 6: CULVERT JUST EAST OF LOCATION ENTRANCE IS FILLED WITH SEDIMENT. Install or repair required BMPs per Rule 1002.f.(2)C. CA DATE 9-9-2023.





PHOTO 7: CULVERT ABOUT 100 YARDS EAST OF LOCATION ENTRANCE IS FILLED WITH SEDIMENT. Install or repair required BMPs per Rule 1002.f.(2)C. CA DATE 9-9-2023.

