

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



SE Entrance of Location – Photo #05573



NE Corner of Location – Photo #05574

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



NW Corner of Location – Photo #05575



SW Corner of Location – Photo #05576

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



Wellheads – Photo #05577



Separators – Photo #05579

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



Tank Battery – Photo #05580



Tank Label Does Not State Capacity – Photo #05581

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



Separator Hatch Unsecured – Photo #05583



Separator Hatch Unsecured – Photo #05584

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



Rill Erosion Cutting Through Lease Road – Photo #05610



Rill Erosion Cutting Through Lease Road – Photo #05613

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SWSE

Location ID: 334846

Date: 8/7/2023



Check Dam Needs Maintenance – Photo #05611