

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



**NW Corner of Location – Photo #05586**



**SW Corner of Location – Photo #05587**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



SE Corner of Location – Photo #05588



NE Corner of Location – Photo #0

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



Aug 7, 2023 at 12:22:35  
Garden Gulch  
Parachute CO 81635  
United States



Aug 7, 2023 at 12:23:46  
Garden Gulch  
Parachute CO 81635  
United States

Wellhead – Photo #05590

Separator – Photo #05592

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



Tank Battery – Photo #05593



Tank Label Does Not State Capacity – Photo #05594

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



**Location Lacks Stabilization – Photo #05596**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05598**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



Rill Erosion Cutting Through Lease Road – Photo #05610

Rill Erosion Cutting Through Lease Road – Photo #05613

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 8/7/2023



**Check Dam Needs Maintenance – Photo #05611**