



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type			
Comment:	See Inspection Doc # 702402179 for related shared facilities and equipment.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	undesirable plant species growing around the WH.		
Corrective Action:	comply with Rule 606.	Date:	08/11/2023

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:	See Inspection Doc # 702402179 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag panel		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	exposed at surfsc		
Corrective Action:		Date:	
Type:	#		
Comment:	See Inspection Doc # 702402179 for related shared facilities and equipment.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:	See Inspection Doc # 702402179 for related shared facilities and equipment.	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 242172 Type: WELL API Number: 123-09963 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Thursday 8-3-2023 at approximately 1515 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: Oxy/Kerr McGee                      Location name: UPRR Pan Am E 2                      API # 05-123-09963                      County: Weld                      Weather: Cloudy light rain.                      Location: Dry.                      While there, I observed a Wellsite SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issues:                      606 House Keeping: CA date 8-11-2023.                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403486403	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6206713">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6206713</a>
702402184	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6206703">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6206703</a>