

Inspection Photos

API: 071-07391

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/8/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 1. Facing northwest east along the access road traveling from the SECO CANYON 11-22 location. Stormwater is bypassing the culvert causing erosion. The road is not stabilized and gravel has washed away.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 2. Facing northwest east along the access road traveling from the SECO CANYON 11-22 location. Stormwater is bypassing the culvert causing erosion. There is an erosion gully forming at this culvert.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 3. Facing northeast east along the access road toward the location. The road is not stabilized and gravel has washed away.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 4. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 5. Facing northeast east along the access road near the location. The road is not stabilized and gravel has washed away.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023

Inspection Photos



Photo 6. This culvert near the location is partially full of sediment and stormwater is bypassing the culvert causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07391 | Date: 8/8/2023