

Inspection Photos

API: 071-07829

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/8/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: 8/8/2023

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



Inspection Photos



Photo 2. Facing toward the pit which is above freeboard level and is not constructed to allow adequate freeboard. There appears to be whitened soils where water may have over flowed toward the red arrow direction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: 8/8/2023

Inspection Photos



Photo 3. The water level is above freeboard and lays flat n the ground which does not show proper freeboard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: 8/8/2023

Inspection Photos



Photo 4. Facing southeast toward the wellsite. There appears to be whitened soils where water may have over flowed toward the red arrow direction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: 8/8/2023