

**Inspection Photos**  
**Location Name: Perrin-Mahoney #2**  
**Location ID: 336295**



Colorado Energy & Carbon Management Commission  
08/08/2023 14:22:36

**Photo 1 Location**



Colorado Energy & Carbon Management Commission  
40.12941, -104.91223, 4913.6ft  
08/08/2023 14:23:39

**Photo 2 WH sign.**



**Inspection Photos**  
**Location Name: Perrin-Mahoney #2**  
**Location ID: 336295**



**Photo 3 Undesirable vegetation around the WH.**



**Photo 4 Stained soil at the WH flow line valve, Undesirable vegetation.**



**Inspection Photos**  
**Location Name: Perrin-Mahoney #2**  
**Location ID: 336295**



**Photo 5 Stained soil at the WH flow line valve, Undesirable vegetation .**



**Photo 6 Undesirable vegetation around location.**

**Inspection Photos**  
**Location Name: Perrin-Mahoney #2**  
**Location ID: 336295**



**Photo 7 Undesirable vegetation around ancillary equip.**



**Photo 8 Undesirable vegetation around location.**



**Inspection Photos**  
**Location Name: Perrin-Mahoney #2**  
**Location ID: 336295**



**Photo 9 Undesirable vegetation and trash around ancillary equip.**



**Photo 10 Undesirable vegetation and trash around location.**