

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



Location entrance sign. Additional information required as signs are replaced.


Entrance to location



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



Debris



Debris



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



Debris



Debris



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



**Debris**



**Debris. Soil staining.**



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



Well sign missing required information



Well sign missing required information



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 11SESE  
Loc ID: 335771



**Well sign missing required information**



**Unmarked anchor**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 11SESE**  
**Loc ID: 335771**



**Location from Northwest corner**



**Location from Southwest corner**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 11SESE**  
**Loc ID: 335771**



**Location from Southeast corner**



**Location from Northeast corner**