

Inspection Photos
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4906 From entrance to location



Photo # 4907 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4908 Location



Photo # 4909 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4910 Location



Photo # 4911 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4954 Stained gravel



Photo # 4955 Stained gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4930 Secondary containment liner needs maintenance



Photo # 4931 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4932 Secondary containment liner needs maintenance



Photo # 4933 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4934 Secondary containment liner needs maintenance

Photo # 4988 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4937 Secondary containment liner needs maintenance



Photo # 5000 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4941 Secondary containment liner needs maintenance



Photo # 4942 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4943 Secondary containment liner needs maintenance

Photo # 4944 Secondary containment liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4947 Secondary containment liner needs maintenance



Photo # 4948 Secondary containment liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC J23NW Pad
Location #: 335405



Photo # 4949 Secondary containment liner needs maintenance



Photo # 5950 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4951 Secondary containment liner needs maintenance

Photo # 4952 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC J23NW Pad

Location #: 335405



Photo # 4953 Secondary containment liner needs maintenance