

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2023

Submitted Date:

08/04/2023

Document Number:

707800526

**FIELD INSPECTION FORM**

Loc ID 334920 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270608	WELL	PR	12/04/2003	GW	045-09567	PA 531-6	PR
270609	WELL	PR	07/16/2004	GW	045-09568	PA 31-6	PR
270610	WELL	PR	07/12/2004	GW	045-09569	PA 331-6	PR
270611	WELL	PR	07/21/2004	GW	045-09570	PA 431-6	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
 On Thursday 8/3/2023, I, Inspector Scott Ramsey, conducted a routine inspection at TEP PA 31-6, at Location # 334920 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.  
 During this inspection the following compliance issues were observed:  
 1. Cut slope is lacking stabilization.  
 2. Culverts need maintained.  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:	Pipe on tank is open to atmosphere	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>270608</u>	Type:	<u>WELL</u>	API Number:	<u>045-09567</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>270609</u>	Type:	<u>WELL</u>	API Number:	<u>045-09568</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>270610</u>	Type:	<u>WELL</u>	API Number:	<u>045-09569</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>270611</u>	Type:	<u>WELL</u>	API Number:	<u>045-09570</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					

Comment:   
 1. Cut slope is lacking stabilization.   
 2. Culverts need maintained.

Corrective Action: **Install, maintain or repair required BMPs**

Date: 09/15/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403487255	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208353">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208353</a>
707800531	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208324</a>