

Inspection Photos
Location Name: CAERUS PICEANCE LLC J18 Pad
Location #: 334865



Photo # 5169 From entrance to location



Photo # 5170 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC J18 Pad
Location #: 334865



Photo # 5171 Location



Photo # 5172 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC J18 Pad
Location #: 334865



Photo # 5175 Location



Photo # 5179 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC J18 Pad

Location #: 334865



Photo # 5181 Stained gravel