

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



South End of Location – Photo #05710



North End of Location – Photo #05711

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



Wellheads – Photo #05712



Separators – Photo #05716

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



Tank Battery – Photo #05715

Location Lacks Stabilization – Photo #05713

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



Location Lacks Stabilization – Photo #05717



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05718**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



Rill Erosion Cutting Through Lease Road – Photo #05693

Rill Erosion Cutting Through Lease Road – Photo #05694

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 8/9/2023



Check Dam Needs Maintenance – Photo #05707

Check Dam Needs Maintenance – Photo #05708