

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



SE Entrance to Location – Photo #05720



NE Corner of Location – Photo #05721

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



NW Corner of Location – Photo #05722



SW Corner of Location – Photo #05723

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



Wellheads – Photo #05724



Separators – Photo #05729

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



Tank Battery – Photo #05726



Open-Ended Vent – Photo #05728

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



Location Lacks Stabilization – Photo #05727



Location Lacks Stabilization – Photo #05730

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05731**



Rill Erosion Cutting Through Lease Road – Photo #05732

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 8/9/2023



Rill Erosion Cutting Through Lease Road – Photo #05733



Rill Erosion Cutting Through Lease Road – Photo #05734