

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5324 From entrance to location**



**Photo # 5325 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5326 Location**



**Photo # 5327 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5328 Location**



**Photo # 5329 Unused equipment/supplies**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC P13WB Pad

Location #: 334658



**Photo # 5331 Stained gravel in secondary containment**



**Photo # 5332 Stained gravel in secondary containment**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5333 Stained gravel in secondary containment**



**Photo # 5334 Stained gravel in secondary containment**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5335 Stained gravel in secondary containment**

**Photo # 5336 Stained gravel in secondary containment**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P13WB Pad**  
**Location #: 334658**



**Photo # 5338 Debris**