

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2023

Submitted Date:

08/05/2023

Document Number:

698600873

FIELD INSPECTION FORMLoc ID 336869 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Hickey, Mike		michael.hickey@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280169	WELL	PR	07/01/2021	GW	125-09516	BLEDSE 16-23-5-45	PR

General Comment:

Routine Inspection.

Location					
Lease Road:					
Type	Access				
comment:	Two track off maintained county road. Two track has not been maintained.				
Corrective Action	Repair and maintain lease road to comply with rule 603.l.				Date: 09/06/2023
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Well sign located inside well fencing.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency contact #877-425-4882 posted on well sign is invalid and appears to be disconnected or no longer in service.				
Corrective Action:	Install sign to comply with Rule 605.a.				Date: 09/06/2023
Good Housekeeping:					
Type	DEBRIS				
Comment:	Production related debris left inside wellhead fencing.				
Corrective Action:	Comply with Rule 606				Date: 08/23/2023
Type	WEEDS				
Comment:	Vegetation growth inside fencing and around wellhead.				
Corrective Action:	Comply with Rule 606				Date: 08/14/2023
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Stock Panel Fencing around surface equipment at well location.				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Other	# 1				
Comment:	Metal Meter Shed.				
Corrective Action:					Date:
Type: Bradenhead	# 0				
Comment:	Bradenhead inaccessible or not visible.				
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).				Date: 08/17/2023
Type: Prime Mover	# 0				
Comment:	Removed.				

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inside Meter Shed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 1-2-23. Meter Calibration/Test Log dated 7-24-20. Well Inlet Valve- Closed. Gas Outlet valve open. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/06/2023
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing in wellbore. Tubing valve closed. Casing valve closed. Supply gas valve closed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Located 3 marked Deadmen.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement Pad. Pump Jack has been removed but cement pad is still inside fencing.		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Removed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 280169 Type: WELL API Number: 125-09516 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Pump Jack removed. Rods and tubing in wellbore. Tubing valve closed. Casing valve closed. Well inlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Current production configuration has the well as SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: **Submit required Form 7(s) to COGCC per rule 413.**

Date: 09/06/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403487621	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209259
698600890	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209258