

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



NW Entrance to Location – Photo #05736



SW Corner of Location – Photo #05737

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



SE Corner of Location – Photo #05738



Wellheads – Photo #05739

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



Separators – Photo #05740



Tank Battery – Photo #05742

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



Aug 9, 2023 at 11:48:12
Parachute, CO 81635
United States



Aug 9, 2023 at 11:48:50
Parachute, CO 81635
United States

Location Lacks Stabilization – Photo #05743

Location Lacks Stabilization – Photo #05744

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05745**



Rill Erosion Cutting Through Lease Road – Photo #05756

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 8/9/2023



Rill Erosion Cutting Through Lease Road – Photo #05769



Check Dam Needs Maintenance – Photo #05755