

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 8/9/2023



South Entrance to Location – Photo #05747



North End of Location – Photo #05748

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 8/9/2023



Wellheads – Photo #05753



Separators – Photo #05751



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 8/9/2023



**Tank Battery – Photo #05752**



**Location Lacks Stabilization – Photo #05749**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 8/9/2023



**Location Lacks Stabilization – Photo #05750**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05754**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 8/9/2023



**Rill Erosion Cutting Through Lease Road – Photo #05756**



**Check Dam Needs Maintenance – Photo #05755**