

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



NW Entrance to Location – Photo #05759



SE Corner of Location – Photo #05760

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



Wellheads – Photo #05761



Wellhead – Photo #05764

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



Separators – Photo #05763



Tank Battery – Photo #05762

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



Location Lacks Stabilization – Photo #05765



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #05766

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



BMP Needs Maintenance – Photo #05767



Rill Erosion Cutting Through Lease Road – Photo #05769

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESW

Location ID: 334817

Date: 8/9/2023



Lease Road Lacks Stabilization – Photo #05770