

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 5510 From entrance to location



Photo # 5511 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 5512 Location



Photo # 5515 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 1661 From Inspection 708900841 conducted on 06/23/2023 Weeds/undesirable plant species in secondary containment



Photo # 5516 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 1662 From Inspection 708900841 conducted on 06/23/2023 Weeds/undesirable plant species in secondary containment



Photo # 5517 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 1664 From Inspection 708900841 conducted on 06/23/2023 Weeds/undesirable plant species in secondary containment



Photo # 5520 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 1665 From Inspection 708900841 conducted on 06/23/2023 Weeds/undesirable plant species in secondary containment



Photo # 5523 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940



Photo # 5517 Weeds/undesirable plant species in secondary containment



Photo # 5518 Weeds/undesirable plant species in secondary containment