

# Inspection Photos

API: 061-06742

Operator: NEWELL ENERGY LTD

Inspection Date: 8/9/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 1.** Facing east at the access road. The cattleguard has filled in with sediment and there is erosion along the road shown at red arrow. There is also undesirable weeds (Russian thistle - dark green) growing along the road that needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 2.** Facing northeast along the access road. The road was reclaimed however, there are undesirable weeds (Russian thistle - dark green) growing along the road that needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 3.** Facing northeast along the access road. The road was reclaimed however, there are undesirable weeds (Kochia) growing along the road that needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 4.** Facing northeast toward the location. The well has been plugged and abandoned and all equipment is removed. Reclamation was performed however desirable vegetation is not establishing and there are undesirable weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 5.** Facing east at the location. This area where the former tank battery was located is bare of vegetation and may have impacted soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 6.** This area where the former tank battery was located is bare of vegetation and may have impacted soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 7.** East of the location facing west. There appears to be impacted soils downhill east of the location.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 8.** 2015 aerial photos shows signs of impacted soil east of the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023

## Inspection Photos



**Photo 9.** Facing south toward the surrounding undisturbed CRP grassland which shows uniform vegetation cover with little to no undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06742 | Date: 8/9/2023