

Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/9/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 1. Facing north along the access road. This portion of the road has not been recontoured and reclaimed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 2. Facing northwest toward the two access road to the former tank battery and wellsite. There is desirable vegetation germinating but dark green vegetation is undesirable weeds that will need to be controlled (e.g. mowed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 3. Facing northwest toward the former tank battery site located 300' southwest of the well site. The dark green vegetation is undesirable weeds that will need to be controlled (e.g. mowed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 4. View of groundcover shows some desirable vegetation beginning to establish.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 5. Facing northeast toward the former wellsite. The dark green vegetation is undesirable weeds that will need to be controlled (e.g. mowed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023

Inspection Photos



Photo 6. Facing north along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/9/2023